•								
Work Order ID 58690  Monday, May 17, 2010 8:26:15 AM							1	Page 1
Item ID: D3913-7 Revision ID: Item Name: Rib		Accept					Setup Star	
Start Date: 5/17/2010 Start Qty: 6. Required Date: 5/21/2010 Req'd Qty: 6. Reference:			Cust Item 1 Customer:	ID:				`
Approvals: Process Plan: QC:	Date: 16-5-1	Tooling:  SPC (Y/N):		ate:		]	Run Star Sto	
Sequence ID/ Operation Work Center ID Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Insp. Number Stamp
Draw Nbr Revision Nbr								
D3913 A							Л	
Large Fab  Large Fab  1 - Cut 2 - rem	tube as per dwg D3913 ove identification marks and de	0.00 0.00 burr			6	9	0610	0.06.01
QC5- Inspect part of QC5- Inspect part of QC5- QC	completeness to step on W/O	0.00 5 10(	56 (O)			To.	)	
120 Identify as per dwg Packaging Memo Packaging	& Stock Location: WA	0.00 SA	D 06-01			6		

Packaging Packaging

Dart Aerospace Ltd	Dart	<b>Aeros</b>	pace	Ltd
--------------------	------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	ES	·	· · · · · · · · · · · · · · · · · · ·			
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
·										
Part No	:	PAR #:	Fault Cat	egory:	_ NCR	: Yes 1	lo DQA:		Date:	
	Re	esolution:	Dispositi	on:	QA:	N/C Clo	sed:		Date:	
NCR:	5	V	VORK ORE	DER NON-CONFORM	ANCE	(NCR)	)			<u> </u>
DATE	STEP	Description of NC	Corrective Action Section   Initial   Action Description			Sign &	Verifica		Approval	Approval
		Section A	Chief Eng	Chief Eng		Date	Section	1 C	Chief Eng	QC Inspector
									-	
		}								
		,				- n - 11				
	-									

#### Work Order ID 58690

Monday, May 17, 2010 8:26:15 AM



Page 2

Item ID:

D3913-7

Accept

Setup Start



**Revision ID:** 

**Start Date:** 

Item Name: Rib

Start Qty: 6.00 5/17/2010

Req'd Qty: 6.00



**Cust Item ID:** 

**Customer:** 

Draw

Number

Reference:

А	nnr	กงล	Is:

Process Plan:

Date:

Tooling:

Date:

Draw

Rev.

Plan

Code

Qty

Start

Stop



Required Date: 5/21/2010

QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID** 

130

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Memo

Set Up/ **Run Hours** 

0.00

0.00

Accept

Run

Reject Qty

Reject Insp. Number

Stamp

10/06/0198) BS10-6-01

Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	GES				· · · · · · · · · · · · · · · · · · ·		
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				•	:						
Part No	:	PAR #:	Fault Cat	egory:	_ NCI	R: Yes N	lo <b>DQ</b>	\	Date:		
	R	esolution:	Dispositi	on:	QA:	N/C Clo	sed:	<u>-</u>	Date:		
NCR:		V	VORK ORE	DER NON-CONFORM	ANCE	(NCR)				·	
DATE	STEP	Description of NC Section A	Initial	Corrective Action Sec Action Description	Cian e Veri				/erification Approval Section C Chief Eng		
		Section A	Chief Eng	Chief Eng		Date	Secti	on C	Chief Eng	QC Inspector	
	.;										
					,						
									·		
							•			•	

**Picklist Print** 

Monday, May 17, 2010 8:26:19 AM

Work Order ID: 58690

Parent Item:

Comments:

D3913-7

Parent Item Name:

Rib



IPP Rev:A new issue DD 10.03.19 verified by:EC

**Start Date:** 5/17/2010

Required Date: 5/21/2010

Page 1

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	Status
M304TS0.500W.049		Purchased	No		100	f	28.6546	1.594		7	

Square Tubing

Location	Loc Qty	Loc Code	
MAT	13.6499		
114426	13.6499		
MAT018	15.0047		
114004	3.5		
114161	11.5047		

		- <del></del>									
W/O:			W	ORK ORD	ER CHANG	ES		7.			
DATE	STEP	PR	OCEDURE CH	ANGE		E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
·											
Part No	•	PAR #:	Fault Cate	egory:		NCR:	Yes N	10 <b>DQ</b>	A:	_ Date: _	
		olution:									
NCR:		,	WORK ORD	ER NON-C	ONFORMA	ANCE (	VCR)				-
DATE	STEP	Description of NC	Corrective Action Section B					Verific	ation	Approval	Approval
	J.E.	Section A	Initial Chief Eng	Action	<b>Description</b> Chief Eng		ign & Date	Secti		Chief Eng	QC Inspector
						Ī					
							<del>- 11 </del>				
						· · ·	<u>.</u>				
										÷	


RETURN TO QTY -041 ITEM ENCHNELE DESCRIPTION D3913-041 LONG BASKET BASE ASSY (350) UNCONTROLLED COTY X SUBJECT TO AMENING D3913-101 TUBULAR ASSY (350 SHORT BASKET) 2 D3913-15 WIDE HANDLE PLATE 1 WITHOUT IN THE F D2581 MOUNTING BRACKET 3 2 WORK ORLAND. 5 8690

BS10-5-17 4 D2931 BUMPER HINGE HALF, BASE 3 D4016-1 D4020-1 MESH (350 BASKET LONG BASE) D4020-11 END MESH, BASKET -8 D4021-1 HANDLE PLATE D4021-5 BLANKING PLATE AN3-10A BOLT 11 AN960JD8 WASHER 2 MS20600AD4W3 BLIND RIVET 10 (14 (14 (13 13 6 MS21042L3 NUT 14 12 NAS1149F0332P WASHER 4 (11)(12) 13 14 14 10 **PELEASE** 2010 -03-22 D3913-041 LONG BASKET BASE ASSY (350) (MESH SHOWN LOCALLY FOR CLARITY) A NEW ISSUE JPH 10.03.16 NOTES: 1) MATERIAL: N/A REV. DESCRIPTION BY DATE 2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED 4) UNITS: INCHES UNLESS OTHERWISE NOTED 5) BREAK SHARP EDGES: NA DESIGN DART AEROSPACE LTD DRAWN HAWKESBURY, ONTARIO, CANADA DRAWING NO. CHECKED REV. A 5) BREAK SHARP EUGES: NA 6) IDENTIFICATION: NONE 7) WEIGHT: 43.3 Ibs APPROX 8) INSTALL AFTER FINISH 9) MASK HOLES PRIOR TO POWDER COAT 10) WELD PER DART QSI 004 D3913 MFG. APPR. APPROVED TITLE LONG BASKET BASE ASSY (350) NTS DE APPR. COPYRIGHT © 2010 BY DART AEROSPACE LTD DATE 10.03.16

5


8

W/O:			ORK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	e Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-			
Part No	:	PAR #:	Fault Cat	egory:	NCR: Ye	s No 1	DQA:	_ Date: _	
		esolution:							
NCR:			WORK ORI	DER NON-CONFORM	JANCE (NO	CR)			
DATE	STEP	Description of NC		Corrective Action Section			rification	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	n Sigi Da	ו אַרן	Section C	Chief Eng	QC Inspector
									<u> </u>
							-		
			1		ı	l			




de

W/O:			W	ORK ORDER CHANG	GES	<del></del>				
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•							
							ļ			
Part No	:	PAR #:	Fault Cate	egory:	_ NCR:	Yes	No DQA	:	Date:	
	R	esolution:	Disposition	on:	QA: I	VC CIO	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORM	ANCE	NCR	)		<u> </u>	
DATE	STEP	Description of NC	Corrective Action S				Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
								:	:	
	ļ									




W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CH	ÄNGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						İ				
Part No	•	PAR #:	Fault Cate	egory:	NCR	: Yes	No DQA	\:	Date:	<u> </u>
	Re	esolution:	Disposition	on:	QA:	N/C Cid	sed:		Date: _	
NCR:			WORK ORE	ER NON-CONFORM	ANCE	(NCR	)			
DATE STEP		Description of NC					Verific	ation	Approval	Approval
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
						<u>.</u>	<del> </del>			
								:		
	]									




Dart	Aer	osp	ace	Ltd
------	-----	-----	-----	-----

W/O:			NGES	; · · · · ·								
DATE	STEP	. PI	ROCEDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						;						
				-						,		
	-		•					i.				
			<u> </u>	· · · · · · · · · · · · · · · · · · ·								
Part No:		PAR #:									<del></del>	
Resolution:							•			Date:		
NCR:	* .	WORK ORDER NON-CONFORMANC					CE (NCR)					
DATE	STEP	Description of NC Section A	Initial Chief Eng	·	ve Action tion Descripti	Section B	Sign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector	
».												
	; ;						. • · · · · · ·					
		·										
	1											
						;	•					



W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	CEDURE CH	IANGE			Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No: PAR #:				It Category: NCR: Yes No				o DQA	DQA: Date:			
Resolution: Dispos			_ Disposit	ion:		QA: N	/C Clos	sed:		Date:		
NCR:		W	ORK OR	DER NON-C	ONFORMA	NCE (	NCR)					
DATE	STEP	Description of NC	Corrective Action Section B				Verifica			Approval	Approval	
		Section A	Initial Chief Eng		Description lief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector	
										-	_	
	·			,								



**D3913-15 WIDE HANDLE PLATE** 

NOTES:
1) MATERIAL: 304/316 STAINLESS STEEL SHEET ANNEALED 2B FINISH,
PER MILLS-5059 OR AMS 5513/5524 OR ASTM A240 OR ASME SA240
REF DART SPEC M304S11GA
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 0.31 lbs

8

w/o 58690

DESIGN	AJS	DART AEROSPACE LTD				
DRAWN	JFH	HAWKESBURY, ONTARIO, CANADA				
CHECKED		DRAWING NO. REV. A				
MFG. APPR.	M.	D3913 SHEET 6 OF 6				
APPROVED	#	TITLE SCALE				
DE APPR.	4#	LONG BASKET BASE ASSY (350) NTS				
DATE 10.0	3.16	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PREMATE AND CONTRIBUTION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR CONTRIBUTION TO BE USED FOR ANY PURPOSE OR TO COMPANY THE TO DAY OF DIRECT PERSON WITHOUT				

Dart Aerospace	Ltd
----------------	-----

W/O:	WORK ORDER CHANGE						ES .								
DATE	STEP PROCEDURE CHANGE					Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
			٠.												
			`.				•								
Part No	:	PAR #:	Fault Ca	tegory:	N	CR: Yes	No DQA	۱:	_ Date: _						
			Disposit	Disposition:				QA: N/C Closed: Date:							
NCR:			WORK OR	DER NON-CONF	ORMANO	E (NCR	3)	- 19,							
DATE STEP		Description of NC Section A	Initial Action Description		Section B iption	Sign &	Verific Section		Approval Chief Eng	Approval QC Inspector					
			Chief Eng	Chief Eng	<u> </u>	Date			· · · · · ·						
							-								
					- ,										
						!									
i.		٠.								****					